


# 10C/28C


## O'Hare Operations October 17, 2013

Presented to: O'Hare Chief Pilots, Mechanics,  
Ramp Operations, CDA Operations

By: Kevin Markwell, Support Manager, ORD

Date: December 4, 2012









# O'Hare Airport



Federal Aviation  
Administration



JetPhotos.Net - Image Copyright © Pete



Federal Aviation  
Administration



Federal Aviation  
Administration

# What are we here for?


- **Changes in the airport surface over the next 10 months**
- **Airspace changes starting next month and continuing through 10/13**
- **Operating configurations on 10/13**
  - Arrival Flows
  - Departure Flows



# 2013 Construction



# South SID's (1/10/13)



# Route Amendments

AAL1257	6263	KORD	KORD MZV J18 STJ./KPHX	
MD82/Q	P1450			2V=
534	340		ONRP	<i>240</i>

FLG3662	6244	KORD	+EARND MACES VHP SHB CEGRM	
CRJ2/Q <i>bs</i>	P1425		CEGRM2+ <i>2V</i>	<i>180</i>
034	210		KORD MACES VHP SHB./KCVG	

UAL513	3145	KORD		
A319/Q	P1545		KORD ACITO1 ARLYN***KIAH	
702	360		ONR P	



# Route Amendments

Data from 10/21/2012 thru 10/28/2012

ARTCC	Airport	+PLUS+ Routes	Total Departures	Percentage
ZAB	ABQ	451	1276	35%
ZAB	ELP	227	877	26%
ZAB	PHX	750	5106	15%
ZAU	MDW	222	2908	8%
ZAU	MKE	231	1384	17%
ZAU	ORD	760	10134	7%
ZOB	BUF	185	1160	16%
ZOB	CLE	926	2082	44%
ZOB	DTW	750	4772	16%
ZOB	PIT	469	1595	29%
ZFW	DAL	442	2114	21%
ZFW	DFW	904	7338	12%
ZFW	OKC	895	1100	81%
ZHU	AUS	600	1851	32%
ZHU	HOU	474	2197	22%
ZHU	IAH	759	5491	14%
ZHU	MSY	1242	1304	95%
ZHU	SAT	730	2008	36%
ZID	CMH	525	1550	34%
ZID	CVG	591	1676	35%
ZID	IND	318	1831	17%
ZID	SDF	450	1859	24%
ZKC	MCI	225	1517	15%
ZKC	STL	150	2184	7%
ZKC	TUL	504	954	53%
ZMP	MSP	537	4841	11%
ZMP	OMA	3	1067	0%





# PDC (Pre-departure Clearance)

- **RNAV ACFT CLEARED VIA ASSIGNED RNAV SID**
- **NON-RNAV EQUIPPED ACFT CLEARED VIA ORD 6**
- **ALL AIRCRAFT MAINTAIN 5000'**
- **REFER TO SID FOR DEP FREQ**
- **CALL 121.67 WITH GATE OR LOCATION**
- **UNLESS OTHERWISE ADVISED BY ATIS**



# Taxiway Name Changes






**Taxiways with Changes**


- Taxiway ZC becomes AA
- Taxiway ZD becomes L1
- Taxiway ZE becomes BB
- Taxiway ZF becomes CC







# WK/WT (July 2013)




# Runway Name Change 5/2/13




# West SIDs




# VFR West Flow (Runways)




# VFR West Flow (Taxiways)







# MVFR/IFR West Flow (Runways)




# MVFR/IFR West Flow (Taxiways)




# VFR East Flow (Runways)




# VFR East Flow (Taxiways)




# MVFR East Flow (Runways)




# MVFR East Flow (Taxiways)





# IFR East Flow (Runways)




# IFR East Flow (Taxiways)



# Intersection Departures



# Arrival Runways



# Standard Taxi Routes

- **Must have Letter of Agreement with tower**
- **Will be airline specific**
- **Reduce verbiage**
- **Easier to pre-brief routes**



# Contact Information

- **Kevin Markwell**
  - 773-601-7693
  - [kevin.marwkell@faa.gov](mailto:kevin.marwkell@faa.gov)
- **PDC**
  - Jeff Molsen
    - 773-601-7638
    - [jeff.molsen@faa.gov](mailto:jeff.molsen@faa.gov)
  - Norm Leader
    - 773-601-7660
    - [norm.leader@faa.gov](mailto:norm.leader@faa.gov)
- **Standard Taxi Routes**
  - Bill Spencer
    - 773-601-7866
    - [bill.spencer@faa.gov](mailto:bill.spencer@faa.gov)





**QUESTIONS??**

**What will you do with this?**



Federal Aviation  
Administration